

Component Placing, Electrical


Applicable for Z520a, Z520c, Z520i, Z525a, Z525i

Contents


1	Component Placing (Antenna Section)	2
2	Component Placing (Primary Side)	3
3	Component Placing (Secondary Side)	4
4	Revision History	5




1 Component Placing (Antenna Section)



2 Component Placing (Primary Side)



3 Component Placing (Secondary Side)



- 1 - Calibration Required
- 2 - Baking Required
- 3 - BGA Rework Equipment Required



4 Revision History

Rev.	Date	Changes / Comments
A	2005-Aug-11	Initial Release
B	2006-Jan-09	Removed Bluetooth, position number N1101. This part must not be replaced. Added positions R1242 and R1245.
C	2006-Apr-11	Corrected arrow positions for V512 and V506. Added model Z525a.
D	2006-May-01	Add V608 to secondary side near microphone.
E	2006-May-15	Added L1206 to RF section.
F	2006-Jun-27	Added model Z525i.
G	2007-Mar-07	Added Antenna Section